Order - No.: DD+DIS355.00E

1 Piece UG2DA MA1

December 2000

Field Service Bulletin No. 14 for

ADC Solo

Type 5155 / 100

Classification			When		
Safety relevant	Reliability	New function	Immediately	Next service	As required
	X			X	

Software Patch SOLG1108 is available now

Order Number:
CM+9.5155.1050.4 SOL_1108 + Patch SOLG1108

Scope of Delivery

- SOL_1108
  4 floppy disks (1 x 'HD formatter' floppy (boot floppy) , 3 x application program floppies)
- SOLG1108: 1 floppy disk
- 1 empty floppy disk
- 1 upgrade instructions (DD+DIS323.00E)
- 1 instructions for the adjustment of the side wall/cassette unit (DD+DIS197.99E)

What is new in Patch SOLG1108

- Patch SOLG1108 solves the sporadic error message 247B0 "repeated checks of the erasure lamps' current flow".

SOLG1108 includes all the previous patches of version SOL_1108.

Please file this document in section 13 of your technical documentation

printed in Germany